



Rear Coil Spring Angle Correction Kit for 1997-2006 Jeep Wrangler TJ and TJD (Unlimited)

NOW SHIPPING!



6" Lift Uncorrected



6" Lift Corrected

NEW!

The factory TJ rear springs are mounted in a "leaning forward" position, which causes the coils to bow excessively rearward once the Jeep is lifted, especially when the suspension compresses. The problem is evident at 3" of lift height, and becomes more of an issue as lift height increases. This incorrect coil loading results in lost ride height and a diminished "too soft" spring rate.

Black Diamond's new Coil Correction Kit includes a pair of weld-on frame brackets and replacement upper coil seats; enough for both sides of one TJ. The frame brackets have adjustment holes that permit the coils and compression travel-dampeners to be in the optimal up-right position, even with wheelbase increases of up to 2". Use with any lift brand, 3" and taller in height.

1997-2006 Jeep Wrangler TJ and TJD (Unlimited)				
Part #	Description	Gen. Trade	UPC	Box Deminsions
810570	Rear Coil Spring Angle Correction Brackets	109.43	804260090289	21.5" x 7" x 5.375"

NOTE:

Welding required. Includes brackets for both driver and passenger side. Use on TJ lifted 3" or more.

